

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOCRAPHS

HABS
HI,
5-LAHA,
1-

Baldwin House
SE corner Front & Dickenson Sts.
Lahaina
Maui County
Hawaii

HABS No. HI-43

Jack E. Boucher, photographer

July 1966

- HI-43-1 GENERAL VIEW OF FRONT
- HI-43-2 OBLIQUE VIEW OF FRONT
- HI-43-3 SIDE VIEW, SHOWING SCAFFOLDING
- HI-43-4 GENERAL VIEW OF REAR
- HI-43-5 REAR WING (DOCTOR'S OFFICE)

Note: All interior view below show the house during a restoration undertaken in 1966.

- HI-43-6 FRONT DOOR AND BOOKCASE
- HI-43-7 FRONT DOOR
- HI-43-8 DOOR AND WINDOW, FIRST FLOOR
- HI-43-9 STAIRCASE, FIRST FLOOR
- HI-43-10 WINDOW, NORTHWEST WALL, FIRST FLOOR
- HI-43-11 WINDOW DETAIL, SHOWING SILL AND LINTEL, FIRST FLOOR
- HI-43-12 SECOND FLOOR, GENERAL VIEW, LOOKING TOWARD STAIRCASE